



Rulebook TECH UPDATE

OHV200 Updates: Lift Check Update

EFFECTIVE DATE: 03/22/2017

Old Rule:

40.4.26.5: Intake lift at retainer .238" max. Exhaust lift at retainer is .242" max.
Lift will be checked as raced.

New Rule:

40.4.26.5: Intake lift at retainer .238" max. Exhaust lift at retainer is .242" max.
Lift will be checked as raced. If running lift checks wrong, retainer can be turned two (2)
times for a re-check of running lift.

Please contact NKA with any questions.

Mike Burrell
NKA Technical Director